



Madicon Firmware Release Notes:

V03 (August 01, 2018)

Under certain circumstances while changing the sample rate the Madicon reported an error (message-stall) to the USB driver. While WIN 10 immediately rejected the USB-device, Mac OS X repeated several times to negotiate the communication with Madicon.